

LAMPS FAIL TO MEET PHOTOMETRIC REQUIREMENTS

1991 Mazda Miata

NHTSA RECALL BULLETIN

Models: 1990 Mazda Miata
1991 Mazda Miata
Number of Affected Vehicles:
Beginning Date of Manufacture: 1990 APR
Ending Date of Manufacture: 1991 MAY

VEHICLE DESCRIPTION:

Passenger cars sold in the United States and Canada.

DESCRIPTION OF DEFECT:

There may be an insufficient amount of reflecting paint on the inner surface of the rear turn signal lamps.

FAULT:

Assembly, Improperly installed, Location, Preparation

SYSTEM:

Turn signal lights.

CONSEQUENCE OF DEFECT:

The lamps failed to meet the photometric requirements of FMVSS 108.

CORRECTIVE ACTION:

Replace the defective turn lamps.

NOTE:

The manufacturer's petition which requested that NHTSA determine this FMVSS non-compliance does not create an unreasonable risk to motor vehicle safety has been granted. Therefore, the manufacturer is not obligated to conduct an owner notification and remedy campaign.

ADDITIONAL INFORMATION:

The National Highway Traffic Safety Administration operates Monday through Friday from 8:00 AM to 4:00 PM, Eastern Time. For more information call (800) 424-9393 or (202) 366-0123. For the hearing impaired, call (800) 424-9153.